

FIG.5A





FIG.5B



[illegible]

A cross-sectional view of a mechanical assembly. A shaft (10) passes through a housing (49). The shaft has a threaded section (M5) and a flange (45). A sleeve (51) is mounted on the shaft, and a nut (52) is used to secure it. The assembly includes various components labeled with numbers 10, 45, 46, 47, 48, 49, 50, 51, 52, 53, 54.